

052500-072450




FIG. 1




FIG. 2

666290 " 01234560




FIG. 3




FIG. 4




FIG. 5

09342310 - 062999

DISTRIBUTION OF LIGHT
ENTERING INTO FIBER BUNDLE




FIG. 6

00602250 - 01 T 22 44 55 00




FIG. 7




FIG. 8

0934310 - 062990

DISTRIBUTION OF LIGHT
ENTERING INTO FIBER BUNDLE




FIG. 9

669290-07224660




FIG. 10

DISTRIBUTION OF LIGHT
ENTERING INTO FIBER BUNDLE




FIG. 11

09343310 - 062999




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17